



Memoirs[®] Stately | K-2269-8

30-11/16" pedestal/console table bathroom sink








Features

- 8" (203 mm) widespread faucet holes
- Elegant rectangular basin
- Overflow drain



Available Colors/Finishes

Color tiles intended for reference only.

- | | | |
|---|-----|--------------------|
|  | 0 | White |
|  | 96 | Biscuit |
|  | NY | Dune |
|  | 95 | Ice Grey |
|  | 7 | Black Black |
|  | H15 | 150th Spring Green |
|  | V10 | 150th Peachblow |



1-800-4KOHLER (1-800-456-4537)
Kohler Co. reserves the right to make revisions without notice to product specifications.
For the most current specification sheet, go to www.kohler.com USA or www.kohler.ca Canada.
4-15-2026 1:0 - US-CA

THE BOLD LOOK
OF **KOHLER**

Codes/Standards

ASME A112.19.2/CSA B45.1

Technical Information

Number of Deck Holes:	3
Faucet Hole(s) Size:	1-3/8" (35 mm)
Center(s):	8" (203 mm)
With Overflow:	Yes
Drain Hole Diameter:	1-3/4" (44 mm)
Basin Configuration:	Single Bowl
Basin Length:	19" (483 mm)
Basin Width:	14" (356 mm)
Basin Depth:	7-1/8" (181 mm)

Material

- Fireclay
-

Recommended Products/Accessories

K-2267 Bathroom sink pedestal

K-30003 Console table legs for K-2269 Memoirs sink

K-23726 Drain treatment

K-8998 Adjustable P-trap with tubing outlet, 1-1/4" x 1-1/4"

K-23725 Cast iron cleaner


Warranty

See website for detailed warranty information.

KOHLER® One-Year Limited Warranty



1-800-4KOHLER (1-800-456-4537)
Kohler Co. reserves the right to make revisions without notice to product specifications.
For the most current specification sheet, go to www.kohler.com USA or www.kohler.ca Canada.
4-15-2026 1:0 - US-CA



Installation

- Console table or pedestal

Installation Notes

Install this product according to the installation instructions.

NOTICE: Countertop manufacturer or cutter must use the cutout template provided with the product, or a current one provided by Kohler Co. (call 1-800-4KOHLER). Kohler Co. is not responsible for cutout errors when the incorrect cutout template is used.

